Douglas Aircraft Company

July 10, 1992 C6-434-DP-92-033

California Regional Water Quality Control Board - Los Angeles Region 101 Centre Plaza Drive Montery Park, CA 91754

Attention: Technical Support Unit

Subject: Technical Monitoring Report: NPDES Permit No. CA0001414, Compliance File No. 5999, 2nd Gtr. 1992

Gentlemen:

Douglas Aircraft Company is submitting the technical reports on self monitoring work performed according to the specifications contained in Monitoring and Reporting program Number 5799. The enclosures summarize the reporting period at our Torrance facility.

As no chromium compounds are utilized in process which discharge to the #799 discharge outflow, no analysis for chromium was performed.

Please feel free to contact me at (310) 533-5716 if you have any questions or comments regarding this report.

"I declare under penalty of perjury that the forgoing is true and correct", executed on the 10th day of July, 1992.

Respectfully yours,

Daniel Palacios

Senior Plant Engineer

Safety, Health and Environmental Affairs

and Falacios

DOUGLAS AIRCRAFT CO.
19503 S. NORMANDIE AVE.
TORRANCE, CA. 90502
MONITORING AND REPORTING PROGRAM NO. 5999
NPDES PERMIT NO. CA0001414

COMPLIANCE WITH STORM DRAIN EFFLUENT LIMITS

PARAMETER	: CONCENTRA	TION LIMITS	:			;
	: (mg/l)		:			:
	1		:			:DISCHARGE
	: AVERAGE	: MAXIMUM	!		, , , , , , , , , , , , , , , , , , ,	_: EXCEEDS
	:	:	4-24-9 2	5-26-92	6-04-92	: LIMITS
•	:	;	1	;	;	:
pH	: -	: 6.0-9.0	8.3	8.1	8.0	: N
	•	:	:	:	:	}
TEMPERATURE ° F	: -	: 100F	: 70	: 71	: 65	: N
GUADEURER DALIER	:	:	:	:	;	:
SUSPENDED SOLIDS	: 50	: 150	:	•	; 12	; N
SETTLEABLE SOLIDS	: 0.1 pl/l	: 0.3 m1/1	:	:	:	
SELLEHDEE SOFINS	. U.1 M1/1	: 0.3 m1/1	i .	;	: ND	: N
BOD5 @ 20C	: 20	. 60	•	i	: : 4.28	; . N
D0113 E 20G	. 20		•	i	i 4.20	: N
OIL & GREASE	: 10	: 15	•	•	8.67	• • N
·	1	;	:	:	:	
CHROMIUM TOTAL **	: 0.005	: 0.01	•	:	· : **	: N
	;	:	:	:	:	- 14
TOTAL FLOW-GPD	:	1	1500	: 1370	: 1870	; N
	:	:	:	:	:	•

\$\$\text{1}\text{NO ANALYSIS REQUIRED IN LIEU OF STATEMENT THAT NO CHROMIUM COMPOUNDS ARE UTILIZED

REPORT

TRUESDAIL LABORATORIES, INC.

-CHEMISTS - MICROBIOLOGISTS - ENGINEERS

RESEARCH

DEVELOPMENT

TESTING



14201 FRANKLIN AVENUE TUSTIN, CALIF. 92680

AREA CODE 714 • 730-6239 AREA CODE 213 • 225-1564

FAX 714 • 730-6462

CLIENT: Douglas Aircraft Company

Internal Mail Code C6-59 19503 S. Normandie Avenue

Torrance, CA 90502

ATTN:

Dan Palacios

REPORT DATE: 6/26/92

RECEIVED:

4/24/92

Water from Stormdrain Torrance Facility - 4/24/92 P.O. No: T & M 25998C

Monthly Industrial Wastewater Analysis as Required by NPDES Permit #CA0001414, April, 1992

RESULTS

Field Data

Flow, GPD:

1500

Temperature, OF:

70

pH, Units (EPA 150.1)

8.3

Respectfully Submitted, Truesdail Laboratories, Inc.

Thomas Herrin, Manager

Environmental Field Services

REPORT

TRUESDAIL LABORATORIES, INC.

#HEMISTS - MICROBIOLOGISTS - ENGINEERS

RESEARCH - DEVELOPMENT - TESTING



14201 FRANKLIN AVENUE TUSTIN, CALIF. 92680 AREA CODE 714 • 730-6239 AREA CODE 213 • 225-1564

FAX 714 • 730-6462

REPORT DATE:

6/26/92

RECEIVED:

5/26/92

CLIENT:

Douglas Aircraft Company

Internal Mail Code C6-59 19503 S. Normandie Avenue

Torrance, CA 90502

ATTN:

Dan Palacios

Water from Stormdrain Torrance Facility - 5/26/92

P.O. No: T & M 25998C

Monthly Industrial Wastewater Analysis as Required by NPDES Permit #CA0001414, May, 1992

RESULTS

Field Data

Flow, GPD:

1370

Temperature, OF:

71

pH, Units (EPA 150.1)

8.1

Respectfully Submitted, Truesdail Laboratories, Inc.

Thomas Herrin, Manager Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

TRUESDAIL LABORATORIES. INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS TESTING DEVELOPMENT RESEARCH



14201 FRANKLIN AVENUE TUSTIN, CALIF., 92680 AREA CODE 714 · 730-6239 AREA CODE 213 · 225-1564

FAX 714 • 730-6462

CLIENT:

Douglas Aircraft Company

Internal Mail Code C6-59

19503 S. Normandie Avenue

Torrance, CA 90502

ATTN:

Dan Palacios

REPORT DATE: June 26, 1992

RECEIVED: June 5, 1992

LABORATORY NUMBER: 50530

Water from Storm Drain, Next to Site #799 P.O. No: T & M 25998-C

Second Quarter, Analysis as Required by the LACSD NPDES Permit #CA0001414

RESULTS

A representative of Truesdail Laboratories, Inc., sampled the industrial stormwater effluent at the Douglas Facility located in Torrance, California. The sample was taken on June 4, 1992. The sample was composited and analyzed according to the American Public Health Association's "Standard Methods," 17th Edition. The results are as follows:

Flow, GPD Temperature, OF pH, Units (EPA 150.1) 1870 65 8.0

Parameter	Method	MILLIGRAMS PE Detection Limit	R LITER Concentration
Oil and Grease Biochemical Oxygen Demand	413.1	6.0	8.67
	405.1	2.0	4.28
Total Suspended Solids	160.2	4.0	12.0
Settleable Solids (ml/L/hr)	160.5	0.2	ND

*ND=Not detected, below detection limit

Respectfully Submitted, Truesdail Laboratories, Inc.

merce 1 Thomas Herrin, Manager

Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.